

Ar. SACHIN KHARE

ANNEXURE-3

ARCHITECT'S CERTIFICATE

(To be submitted at the time of Registration of the Project)

To,
The **Singhania Buildcon Pvt. Ltd.**, Harshit Corporate, G.E.Road, Raipur (C.G) 492001,

Subject :- Certificate of Percentage of Completion of Construction/Development work in
Archees Icon City ,Baloda Bazar .

Sir,

I **Sachin Khare** have undertaken assignment as Architect for certifying Percentage of Completion of Construction/Development Work of the **Archees Icon City** Project, situated at Village **Orathi**, Tehsil **Simga**, District **Baloda Bazar** admeasuring **85290 Sq.Mtr.** area being developed by **Singhania Buildcon Pvt. Ltd.**

1. Following technical professionals have been appointed by the Promoter :-


- (i) Shri **Sachin Khare**as ~~Land Surveyor~~/Architect;
- (ii) Shri ...**Prashant ku. Bani**as Structural Consultant;
- (iii) M/s **Potential Semac consultant ..** as Mechanical, Electrical, Plumbing Consultant;
- (iv) Shri ...**Santosh Kumar Sahu** Head Site-Supervisor;

Based on Site Inspection, with respect to the aforesaid Real Estate Project, I certify that as on the date of this certificate, the Percentage of Work done, for the Real Estate Project **Archees Icon City** is as per **Table-A** herein below. The percentage of the work executed with respect to each of the activity of the entire phase is detailed in **Table-B**.

For, **Singhania Buildcon Pvt. Ltd.**


Director


SACHIN KHARE
ARCHITECT
Reg.No.-CA/2015/66024



Ar. SACHIN KHARE

Table A

Sr. No	Tasks /Activity	Percentage of work done
1.	Excavation	N/A
2	--- number of Plinth	N/A
3	-- -- number of Podiums	N/A
4	-- - Stilt Floor	N/A
5	-- number of Slabs of Super Structure	N/A
6	Internal walls, Internal Plaster, Floorings within Flats/ Premises, Doors and Windows to each of the Flat/ Premises	N/A
7	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/Premises	N/A
8	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	N/A
9	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/ Wing,	N/A
10	Installation of Lifts, Water Pumps, Fire Fighting Fittings and Equipment, Electrical fittings to Common Areas, Electro, Mechanical equipments, Compliance to conditions of environmental NOC (if any), Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to Obtain Occupation /Completion Certificate	N/A

Ar. Singhania Buildcon Pvt. Ltd.


TABLE-B

Internal & External Development Works in Respect of the entire Project

Director

S. No	Common areas and Facilities, Amenities	Proposed (Yes/No)	Percentage of Work done	Details
1.	Internal Roads & Foot paths	Yes	30%	
2.	Water Supply Line	Yes	35%	
3.	Sewerage (chamber, lines, Septic Tank)	No	N/A	
4.	Sewage Treatment Plant (STP)	No	N/A	
5.	Storm Water Drains	Yes	0%	
6.	Landscaping & Tree Planting	Yes	40%	
7.	Street Lighting	Yes	13%	
8.	Community Buildings/ Club House	NO	N/A	

SACHIN KHARE
ARCHITECT
Reg.No.-CA/2015/6800



Ar. SACHIN KHARE

S. No	Common areas and Facilities, Amenities	Proposed (Yes/No)	Percentage Work done	Details
9.	Solid Waste management & Disposal	No	N/A	
10.	Water conservation, Rain water harvesting	Yes	0%	
11.	Energy Management/Sub-station	Yes	9%	
12.	Fire protection and fire safety requirements	No	N/A	
13.	Open area (Park)	Yes	40%	
14.	Boundary Wall	Yes	95%	
15.	Security Service	Yes	100%	
16.	Others (Option to Add more)			

TABLE C

Overall percentage of the work completed

Sr. No.	Particular	Percentage of work done
1.	Overall percentage of construction/development completed as per Table-A and Table-B.	45%

Date: 27/05/2018

Place: Raipur

For, Singhania Buildcon Pvt. Ltd.

Director

SACHIN KHARE
ARCHITECT

Reg. No. - CA/2015/66024
Signature

Name of the Architect **Sachin Khare**
(License No. 710 /2015....)